Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Improvement of laying curb stones, repairs and painting at Sundaranagara park in Ward No. 17
2	Administration Approval & Date	JC/RRN/AS/2847/2013-14 Dtd.13-02-2014 by JC RRNZ
3	Technical Sanction Estimate No.& Date	EE(P)/RRN/TS/39/13-14 dtd:19-02-2014 by EE(P) (RRN)
4	Estimate Amount	Rs.10.00 Lakhs
5	Job Code No.	017-14-000107
6	P-Code	P -0190 .
7	Agreement No & date	EE/RRN/Proj/AG No./114/2013-14 Dtd.24-02-2014
8	Work order Number & Date	EE/Proj/RRN/W.O/114/2013-14 Dtd.24-02-2014
9	Contract Amount as per Agreement	Rs. 10,00,000/- + KRIDL Charges
10	Bill Amount	Rs.9,28,404/- including KRIDL Charges
11	B.R. No. & Date	191/2014-15 dt.30-07-2014
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	2267/14-15 Pages 226605 to 226616
14	Date of Inspection	3/9/2015
15	Enclosures	1) Extract of MB No.2267 Page No.226616/1 2) 6 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned Officers. The measurements of the Items which are susceptible for measurements have been Checked by me & found to be Satisfactory

Inspection Report returned for I.O to provide further proof

EE(P) RR Nagara

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು (ಯೋಜನೆ)
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಲಯ

3/9/2015

(R.Sathyanarayana)
Inspection Report officer,